

Clean hood to remove dust residue.	Exposure to silica dust by inhalation.	Training, procedures, work planning, areas with limited access to authorized personnel only, personal protective equipment, ventilation hood.	N	1	2	4	2	16								
Fire coated parts	Burns	Training, procedures, work planning, PPE	N	1	2	2	2	8								
Further Description of Controls Added to Reduce Risk: Continual base line personal exposure monitoring for silica is in process for this work to characterize this job more completely.																
*Risk:	0 to 20	21 to 40	41-60	61 to 80	81 or greater											
	Negligible	Acceptable	Moderate	Substantial	Intolerable											