

Instrumentation Group Procedure C-A-INT-002
Original Issue Date: 01/10/02
Revision 02

CHECKLIST FOR USING 30mci Cs137 SOURCE
S/N 1595

* This checklist procedure is to be used by Authorized Source Operators only *

- 1) Upon entering the Calibration Pit the following must be observed:
 - a) The proper postings are in place.
 - b) The door is secured.
 - c) The Source Exposed light is on and operational.
- 2) Verify that the source leak check is up to date.
- 3) Verify that the shielding (lead bricks) is in place and intact.
- 4) Position the device to be calibrated.
- 5) Unlock the source storage pig.
- 6) Open the end of the storage pig to expose the source.
- 7) Open and close the end of the storage pig as needed during calibration.
- 8) When work is completed lock the source storage pig.

AUTHORIZED SOURCE OPERATORS

NAME (PRINT)	NAME (SIGNATURE)	LIFE NUMBER