



Transfer animals to radiological target boxes.	Exposure to anesthetic.	Ventilation of the work area, use of local ventilation, leak testing of apparatus.	N	1	2	2	2	8								
Transfer animals to radiological target boxes.	Scratched or bitten by animal.	Use of PPE, gloves.	N	1	2	2	3	12								
Transport animals in target boxes from A lab to NSRL target room	Ionizing radiation exposure	Work planning, Access control, RWP.	N	1	2	1	2	4								
Remove animals from target room to A lab.	Exposure to anesthetic.	Leak testing of apparatus, ventilation of work area.	N	1	2	1	2	4								
Further Description of Controls Added to Reduce Risk:																
*Risk:	0 to 20	21 to 40	41-60	61 to 80	81 or greater											
	Negligible	Acceptable	Moderate	Substantial	Intolerable											