

			Before Additional Controls						After Additional Controls							
Job Step / Task	Hazard	Control(s)	Stressors Y/N	# of People A	Frequency B	Severity C	Likelihood D	Risk* AxBxCxD	Control(s) Added to Reduce Risk	Stressors Y/N	# of People A	Frequency B	Severity C	Likelihood D	Risk* AxBxCxD	% Risk Reduction
	Cut by sharp object due to breakage of glass thermos dewar	Training, procedures, gloves, eye protection, proper clothing, wrapping dewar with tape	N	1	3	2	2	12								
Further Description of Controls Added to Reduce Risk:																
*Risk:	0 to 20 Negligible	21 to 40 Acceptable	41 to 60 Moderate					61 to 80 Substantial			81 or greater Intolerable					