

| | | | | | | | | | | | | | | | | |
|--|---|--|----------|-------------|---------------|---|---|----|--|--|--|--|--|--|--|--|
| Perform electronic repair. | Use of hand tools | Procedures, training, permits | N | 1 | 3 | 2 | 1 | 6 | | | | | | | | |
| Reset local circuit breakers. | Exposure to electrical shock and flash hazard | Procedures, training, permits, use of PPE as per NFPA 70E, use of insulated tools. | N | 1 | 3 | 1 | 2 | 4 | | | | | | | | |
| Remove LOTO from circuit breaker. | Exposure to electrical shock and flash hazard | Procedures, training, permits, use of PPE as per NFPA 70E, use of insulated tools. | N | 1 | 3 | 4 | 2 | 24 | | | | | | | | |
| Verify operation of equipment | Minimal Hazard | Procedures, training | N | 1 | 3 | 1 | 1 | 3 | | | | | | | | |
| Close out LOTO log. | Minimal Hazard | Procedures, training, permits. | N | 2 | 3 | 1 | 1 | 6 | | | | | | | | |
| Report task completion to Cryogenic's Control Room.. | Minimal Hazard | Procedures, training, permits. | N | 2 | 3 | 1 | 1 | 6 | | | | | | | | |
| *Risk: | 0 to 20 | 21 to 40 | 41-60 | 61 to 80 | 81 or greater | | | | | | | | | | | |
| | Negligible | Acceptable | Moderate | Substantial | Intolerable | | | | | | | | | | | |