

Transport component back to inner Mongolia.	Traffic accident	Licensed drivers, traffic rules and signs, slow speed, spotters, warning/flashing vehicle lights, vehicle maintenance and inspection, Transportation subject area, work planning, pre-job briefing, cribbing, secured load, known route.	Y	2	3	3	1	18								
Lift component off truck and place back in storage area.	Falls from height	Qualified PE riggers, known weight of load, known center of gravity of load, known lifting points of load, inspection and maintenance of equipment, hard hat, gloves, good house keeping, SBMS subject areas, OPM procedures, work planning, work permits.	Y	2	3	3	2	36								
Lift component off truck and place back in storage area.	Falls from same level	Qualified PE riggers, known weight of load, known center of gravity of load, known lifting points of load, inspection and maintenance of equipment, cribbing, hard hat, gloves, SBMS subject areas, OPM procedures, work planning, work permits, PE maintenance of road ways and infrastructure.	Y	2	3	3	1	18								
Lift component off truck and place back in storage area.	Getting struck by dropped load or hitting other objects with load while moving	Qualified PE riggers, known weight of load, known center of gravity of load, known lifting points of load, inspection and maintenance of equipment, cribbing, SBMS subject areas, OPM procedures, work planning, work permits.	Y	2	3	3	2	36								
*Risk:	0 to 20	21 to 40	41-60			61 to 80			81 or greater							
	Negligible	Acceptable	Moderate			Substantial			Intolerable							