



Booster/AGS Ring Power Supply Systems  
Group Procedure EPS-W-004  
Revision 00

#### **15.3.5.4 Westinghouse Oil Pit Confined Space Entry**

The following steps must be performed in order to enter Westinghouse Oil Pit. (CLASS-2A)

1. You must be confined space trained.
2. Read C-A OPM 8.14 Confined Space Entry Procedure.
3. Read the Confined Space Hazard Identification Checklist Sheet before entering.
4. Read the C-A OPM 8.14.a Confined Space Entry Certification Sheet before entering.
5. Take an air sample before entering the confined space and record the levels. Sign, date and record the time of each entry on the Confined Space Entry Certification Log Sheet.
6. Sign out the time work is completed on the Confined Space Entry Certification Log Sheet.