

Table 1: SAFETY OBSERVATION REPORT

Observers: P. Wanderer, K. Krasner		Date: 24July07	Duration: 45 min.			
Observation Categories	Observation Questions:					
POS	In risky position relative to task? NO Exposed to risks of temperature/electricity/gas/chemicals/radiation? no Protection OK? yes					
ERG	Risks from: posture, repetitive motion, load, vibration, temperature, lighting, noise, work flow? no					
PPE	Correct PPE? yes In safe condition? yes All parts of the body properly protected? yes					
T&E	Is tool, equipment or facility right for the job? yes In safe condition? yes Used correctly? yes					
PRO	Is there a standard procedure? Yes (worker planned work) Is procedure adequate? yes Up to date? yes Understood? yes Followed? yes					
ORD	Is workplace orderly? yes Adequate space? yes Is there a place for all materials and equipment? yes All in its place? yes					
ASF	No unsafe acts or conditions identified correct					
Work Area or Location	Number of Contacts	Description of unsafe acts	Observation Category	Follow-up Action	Person Responsible	By Date
Vertical cryo test facility	1	Opportunity for improvement: install safety shield with holes in the sides and a door for adjusting pistons, use tools with longer handles, install black and yellow warning tape on raised concrete step near stairs	POS	Install shield	Ribaudo	10/1/07