

*If you are using a printed copy of this procedure, and not the on-screen version, then you **MUST** make sure the dates at the bottom of the printed copy and the on-screen version match. The on-screen version of the Collider-Accelerator Department Procedure is the Official Version. Hard copies of all signed, official, C-A Operating Procedures are available by contacting the **ESSHQ Procedures Coordinator, Bldg. 911A***

C-A OPERATIONS PROCEDURES MANUAL

ATTACHMENT

8.3.1.b Warning Placard

C-A OPM Procedures in which this Attachment is used.		
8.3.1		

Hand Processed Changes

<u>HPC No.</u>	<u>Date</u>	<u>Page Nos.</u>	<u>Initials</u>
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Approved: _____ *Signature on File* _____
 Collider-Accelerator Department Chairman Date

D. Weiss

8.3.1.b Warning Placard

_____ *Caution* _____

BURN HAZARD

SURFACE
TEMPERATURES
CAN REACH

212°F (100°C)

RHIC Vacuum
x4084