

Alarm Code 943-2
Restore 943-3

Location: B 928/929-RFMG Bldg

Alarm Limits
No Flow

System: Liquid Rheostat - LoFlow

- Action:**
1. **Verify no flow with inlet & outlet press gauges (inlet \approx 43 psig for normal conditions).**
 2. **Check that 2 tower pumps are on.**
 - a) **If not, Note 3.**

- Notes:**
1. **Record Actions Taken**
 2. **MCR = Main Control Room (x 4662)**
 3. **Call Mech Svcs from "Call In" List**

[Back to Top](#)

Alarm Code 943-6
Restore 943-7

Location: B 928/929-RFMG Bldg

Alarm Limits
≥ 100°F

System: MG Lube Oil - Hi Temp

- Action:**
1. Verify Hi temp.
 2. Check for chilled water flow with temp $\approx 50^{\circ}\text{F}$.
 - a) If not, advise MCR and call Plant Engineering's Site Shift Supervisor @ x 4174, cell # 872-8988 or C/W desk x4284.
 - b) Note 3 the following workday.

- Notes:**
1. Record Actions Taken
 2. MCR = Main Control Room (x 4662)
 3. Call Mech Svcs from "Call In" List

[Back to Top](#)

Alarm Code 943-8
Restore 943-9

Location: B 928/929-RFMG Bldg

Alarm Limits
No Flow

System: MG Lube Oil - Lo Flow

- Action:**
1. Verify no chilled water flow.
 2. If not, advise MCR and Call Plant Engineering Site Shift Supervisor at x4174, cell – 872-8988 or C/W desk x4284 during off hours.
 3. Note 3 the following workday

- Notes:**
1. Record Actions Taken
 2. MCR = Main Control Room (x 4662)
 3. Call Mech Svcs from "Call In" List

[Back to Top](#)