

Alarm Code 947-2
Restore 947-3

Location: B 928/929-RFMG Bldg

Alarm Limits
≥ 60 F (Hi)
≤ 40 F (Lo)

System: Chilled Water System - Hi/Lo Temp

- Action:**
1. **Verify temp. condition**
 2. **Advise MCR that RF Cavity and Bldg. A/C will be affected**
 3. **Call Plant Engineering Site Shift Supervisor at x4174, cell – 872-8988 or C/W desk x4284 during off hours.**
 4. **Note 1 & 3 the following workday**

- Notes:**
1. **Record Actions Taken**
 2. **MCR = Main Control Room (x 4662)**
 3. **Call Mech Svcs from "Call In" List**

[Go to Top](#)

Alarm Code **947-4**
Restore **947-5**

Location: **B 928/929-RFMG Bldg**

Alarm Limits
≤ 30 psig

System: **Chilled Water System - LoPress**

- Action:**
- 1. Verify Low Pressure**
 - 2. Call Plant Engineering Site Shift Supervisor at
 x4174, cell – 872-8988 or C/W desk x4284
 during off hours.**
 - 3. Note 1 & 3 the following workday**

- Notes:**
- 1. Record Actions Taken**
 - 2. MCR = Main Control Room (x 4662)**
 - 3. Call Mech Svcs from "Call In" List**

[Go to Top](#)

Alarm Code **947-6**
Restore **947-7**

Location: **B 928/929 RFMG Bldg**

System: **Chilled Water System - Chiller #1 Malfunction**

- Action:**
- 1. Verify Chiller is off**
 - 2. Call Plant Engineering Site Shift Supervisor at
 x4174, cell – 872-8988 or C/W desk x4284
 during off hours.**
 - 3. Advise MCR that RF Cavity and Bldg. A/C will be
 affected**
 - 4. Note 1 & 3 the following workday**

- Notes:**
- 1. Record Actions Taken**
 - 2. MCR = Main Control Room (x 4662)**
 - 3. Call Mech Svcs from "Call In" List**

[Go to Top](#)

Alarm Code **947-8**
Restore **947-9**

Location: **B 928/929 RFMG Bldg**

System: **Chilled Water System - Chiller #2 Malfunction**

- Action:**
- 1. Verify Chiller is off**
 - 2. Call Plant Engineering Site Shift Supervisor at
 x4174, cell – 872-8988 or C/W desk x4284
 during off hours.**
 - 3. Advise MCR that RF Cavity and Bldg. A/C will be
 affected**
 - 4. Note 1 & 3 the following workday**

- Notes:**
- 1. Record Actions Taken**
 - 2. MCR = Main Control Room (x 4662)**
 - 3. Call Mech Svcs from "Call In" List**

[Go to Top](#)